

# Oil Field Environmental Incident Summary

**Incident:** 20141102094044 **Date/Time of Notice:** 11/02/2014 09:40

**Responsible Party:** BOSQUE DISPOSAL SYSTEMS, LLC

**Well Operator:** BOSQUE DISPOSAL SYSTEMS, LLC

**Well Name:** JESSICA SWD 1

**Field Name:** BLUE BUTTES

**Well File #:** 90243

**Date Incident:** 11/1/2014 **Time Incident:** 17:30

**Facility ID Number:**

**County:** MCKENZIE

**Twp:** 150

**Rng:** 95

**Sec:** 23

**Qtr:**

**Location Description:**

**Submitted By:** Al, Hunt

**Received By:**

**Contact Person:** Al, Hunt  
420 THROCKMORTON ST STE 640  
FORT WORTH, TX 76102-3723

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Tank Overflow

**Release Contained in Dike:** Yes - Within Dike

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	6	Barrels	6	barrels		
Other						

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

None

**Areal Extent:**

***Potential Environmental Impacts:***

None

***Action Taken or Planned:***

Better training of employees

***Wastes Disposal Location:***

***Agencies Involved:***

***Updates***

---

***Date:*** 11/3/2014    ***Status:*** Reviewed - Assigned to Other Agency

***Author:*** Roberts, Kris

***Updated Oil Volume:***

***Updated Salt Water Volume:***

***Updated Other Volume:***

***Updated Other Contaminant***

***Notes:***

Release, due to a tank overflow, remained on location within the diking according to the report. NDIC retains oversight.